ENGINEERING CHANGE NOTICE												
DART AEROSPACE LTD				ECN #: 801								
Date: 06,05,02		4.0										
Project No: D205-564 / D430-6	88		Created By:	ted By: Checked By: W								
Project Name:	•		Approved By:									
BEARPAW INSTAL	LATT	ons	(Proj. Manager)	4								
Description of Change:					1 4 4 1 1 1							
RELEASE: DS19328	Re	O, A	•									
D3503 R						1						
D3511 R												
א אוכפע	æ0,											
Engineering Actions	Yes	No	Responsible	To happen by:	Complete	1						
Required Documents Under Review?		V										
Update Blue/Pink Folder/Electronic File	V.		KST/PH	86.05.04	06.05.024 PH	<u>'</u>						
Update DSI Folder/Electronic File	$\overline{}$		KS/PH	06.05.04	06.05.02 AL PH	_						
Update D-Part Master Binder	V		F.F	06.05.04	do.05.02	_						
Update Grey Project Binder		J				06.07.1						
Update DEO/DSI Binder	V.		K5	06.05.04	06.05.024	1/						
Update Master Document List (MDL)		. •	¥5	06.05.04	N/A AF	14						
Update Drawing Approval Record (DR)	\checkmark		2 5	06.05.04	66.05.03	1						
Update Change Record Form	\checkmark		KI	06.05.01	06.05.03	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \						
Move Electronic File	/		45	06.05.05	06.05.05	366						
Notify TCA of Change	√	L.,	D5	06.06.02	Ų.	105						
Notify FAA of Change			·			e-mail						
Update QSI 021 (TC/FAA STC)		<u> </u>										
Update QSI 036 (K-Kits)	ļ	$oldsymbol{\checkmark}$				_						
Scan Documents	<u> </u>	lacksquare				_						
Update Accpac Database	$\downarrow \checkmark$		KT.	06.05.04	ab.05.03 +							
Update Access Database	\bot	—	+3	06.05.04	06,05,03 90-	4						
Verification ARC	lacksquare	ĽV,	K1	06.05.04	06.05.03 48	4						
Create/Update STC Approval List	L,		<i>(</i>		7 . 7 . 7 . 4	-						
Update Prod. Dev. Summary	14			06.05.05	D6,07.18 Rt	-i						
Create/Update COSS (Estimate/BOM)	↓ -,		JLM	06.05.04	06.05,039							
Create/Update PPP's	 Y		+3	06.05.04	06.05.0377	4						
Update Paperwork Kits in Production	14		145	16.05.04	Nome in PADD &	-[
Update Paperwork Kits in Stock	 		45/11	06.05.04	06:05.1160+.	4						
Rework/Scrap Current Production	14/		<u>u</u>	06.05.04	1 00.07.190 45 -	<u></u> ∱						
Rework/Scrap Kits in Stock?	\vee	√	; <u>L</u> L	06,05.04		1 \						
Update Qpulse	/	<u> </u>	+I	2/ 00 21	06.05.02 +	1 \						
Create/Update Controlled PDF Dwgs	 		7-3	86.05.04	06.05.02 19	1 1						
Create/Update FAI sheets		Y	VI A A	dos of	7.11 - 105 -1	4						
Create/Update CNC Programs	 ` /		JLM JLM	0605.05	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1						
Create/Update Tooling	1.		PH	06.05.05	PH 05.05.05	1 /						
Create/Update DXF File MPP required?	 Y 		r n	06.05.05	17 05.05.03 /	1 /						
Notify Previous Customers		-		 		1 /						
Notify Eurocopter France	 	.				1 /						
		لــــــــــــــــــــــــــــــــــــــ	\		12. 200V/61= 1-	1/						
OPDATE RIODIS WI					EWORK (See ATTACHED EMAIL)	/						
o Scrap DSI 9247-011 Kits	+ 1	518	7-041 wearplote		6/	1						
4					KEP DST 9247 in stack	4						
/					see attacked L. Locelly							

ECN Complete:

e-mail

Kim Johnston

From:

phum@dartaero.com

∂ent:

Tuesday, May 02, 2006 2:08 PM

fo:

Kim Johnston

Cc:

davids@dartaero.com; sshahbazian@dartaero.com

Subject:

RE: Run-on Landing Wearplate kit

Hi Kim,

The Change number will be 001 because this is an entirely new DSI and is NOT a revision to the existing DSI. We are treating this as strictly a brand new product. The new DSI P/N makes this part distingushed between the old DSI (b/c not the same P/N) and therefore its at CHG 001. The old DSI should be taken out completely from the blue/pink/production.

The MDL or DR which ever this project has needs to be updated, it will be a David self-audit type because its a TC approval. Since the P/N's for the DSI and drawings are all new, new CNC programs/tooling would need to be created as required by JLM or EC.

You will have to talk to Bill B/David with regards to customers waiting on this dsi.

Peter

Kim Johnston <kjohnston@dartaero.com> said:

> 1) Update Blue/Pink File/

```
Peter,
> Will the change record # go up for these parts because of the dsi? Is
> any change to CNC programs, tooling, any customers waiting on this dsi,
does
> the mdl get updated?
> Kim
> ----Original Message----
> From: phum@dartaero.com [mailto:phum@dartaero.com]
> Sent: Tuesday, May 02, 2006 10:56 AM
> To: S Shahbazian; Hum, Peter
> Cc: Johnston, Kim; davids@dartaero.com
> Subject: Re: Run-on Landing Wearplate kit
>
> Hi Serge,
> Assuming that David has signed off the new DSI and the drawings. This is
> what needs to be done.
> 1) Signed off drawings and DSI from David,
> 2) ECN to release drawings and the DSI
> 3) Scrap the old DSI parts in stock (L Lacelle has told me there is 3) that
> is associated with the 205 bearpaw (D205-564, I think)
  4) The signed off DSI will replace the old DSI
> The ECN should have
```

```
> 2). Scrap in stock/current production as required (DESTROY OLD STOCK)
y > 3) Update COSS/ACCPAC/ESTIMATES/UPDATE DXF FILE (there are new P/N's and
  > estimates to be written), the wearplate will be cut on the waterjet, Eric C
  > should have the file
  > 4) Update DSI folder and drawing binder and the .pdf folder
   5) The paperwork in production/stock needs to be updated (i.e. replace the
  > old wearplate DSI with the new wearplate DSI)
  > I hope I haven't forgotten anything. If I have, or you have questions just
  > ask me or David
  > Peter
  > S Shahbazian <sshahbazian@dartaero.com> said:
  > > Hi Peter,
  > > What is left to be done on Run-on Landing Wearplate Kit? Is it only the
  > > ECN? Are we changing whatever is in stock? Because Kim can do the ECN,
  she
  > > needs to know what to mark on ECN.
  > >
  > >
  > > Thanks
  > >
  > > Serge
  > >
  > >
```

. Lacelle

From:

Bill Beckett [bbeckett@dartaero.com]

Sent:

May 9, 2006 2:16 PM

To:

'Linda Lacelle'

Cc:

Sian Willems (E-mail)

Subject:

RE: ECN 801

Linda,

Don't scrap them, but I don't want to make any more once these are gone. They will be replaced by DSI9328 (in the catalogue as well).

Bill

----Original Message----

From: Linda Lacelle [mailto:llacelle@dartaero.com]

Sent: May 9, 2006 12:34 PM

To: 'Bill Beckett' Subject: RE: ECN 801

Do I scrap the 3 ??

----Original Message----

From: Bill Beckett [mailto:bbeckett@dartaero.com]

Sent: Monday, May 08, 2006 10:26 AM

To: 'Peter Hum'; 'Linda Lacelle' Cc: 'Bill Beckett (E-mail)'

Subject: RE: ECN 801

Linda,

Who in DHS requested the L/T? I need to talk to them.

Bill

----Original Message----

From: Peter Hum [mailto:phum@dartaero.com]

Sent: May 8, 2006 9:47 AM

To: 'Linda Lacelle'

Cc: Bill Beckett (E-mail)

Subject: RE: ECN 801

Better check with Bill, it was my impression that we were scraping them all

Additionally, the old DSI 9247 was replaced by the new DSI 9328. Is it possible they are asking for the new wearplate but using the old DSI # to place the order.

Peter

----Original Message----

From: Linda Lacelle [mailto:llacelle@dartaero.com]

Sent: Monday, May 08, 2006 9:40 AM

To: Peter Hum (E-mail)

Subject: ECN 801

Peter,

Are we sure we want to scrap the 3 x DSI 9247's in stock? I know DHS requested a L/T last week on one of these. Just wanna make sure. $_{\mathsf{L}}$

Date: User: Tuesday, 5/9/2006 2:29:48 PM

Linda Lacelle

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

S.O. No. :

Job Number

: 27038

Estimate Number

P.O. Number

This Issue

: 5/9/2006

: NC

Prsht Rev. First Issue

: 5/8/2006 : 00015

: 10804

Previous Run

Checked & Approved By

Written By

Comment

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

ADD DSI 9328 TO K10015'S IN STOCK

REMOVE DSI 9247 PAPERWORK FROM K10015 KITS IN STOCK

2.0

DC

DOCUMENT CONTROL



Comment: DOCUMENT CONTROL

INSPECT LEVEL 21

Job Completion



B234834 x2 B23912 x 1

B25168 x 7

Drawing Name

: D205-564 (K10015)

: Z CUSTOM

Part Number

Drawing Number

• PAPERWORK

Project Number

Drawing Revision Material

Due Date

: 5/15/2006

Qty:

1 Um:

Each

Page 1

Author intry:		* AUTHOR	IZED RELEAS	\mathbf{E}	3. Form Tracking Number:					
Tran	sporı Canada		TCCA 24-		Wearplate					
1270 Abe Hawkesbu			ROSPACE LTD rdeen Street iry, ON CANADA	Fax: 1 613 Email: heli	Tel: 1 613 632 3336 Fax: 1 613 632 4443 Email: heli@dartaero.com www.dartaero.com		5. Work Order/Contract/Invoice Number:			
6. Item:	7. Description:	8. Part N		gibility: *	10. Quantity:	11. Serial/Batch Number:		12. Status/Work:		
1	1 Run-on Landing Wearplate Kit DSI 932:		-011 Per line 1 of 13, remarks			В .		Manufactured		
13. Remar	l ·ks:					_L		<u> </u>		
	H01-56 Issue 1, FAA STC		formity to:	19.	AR 571.10 Maint	enance Release				
14. Certifies the items identified above were manufactured in conformity to: X Approved design data and are in a condition for safe operation.										
	Non-approved design data	•	ici atton.	Certifi		wise specified in	Block 13, the	work identified in Block dance with CAR 571.		
15. Authorized Signature:			16. Certificate/Approval Ref. N	o.: 20. Authoriz	20. Authorized Signature:		21. Certificate/Approval ref No.			
			/ 09-89		N/A			N/A		
17. Name (Typed or Printed):			18. Date (dd/mmm/yyyy):	22. Name (T	22. Name (Typed or Printed):		23. Date (dd/mmm/yyyy):			
					N/A			N/A		
			User/Inst	aller Responsibil	ities		<u> </u>			
2. Whe	re the installer works in a thiness authority accepts	products or maintenance from	rt. Egulations of an airworthiness autherity spection. In all cases, the aircraft tech	ified in Block 1.						
regulat	ions of the state of registr	y, before the aircraft may be f	lown.				·			

Peter Hum

From: David Shepherd [dshepherd@dartaero.com]

Sent: July 18, 2006 3:51 PM

To: 'Peter Hum'
Cc: 'Kim Johnston'

Subject: RE: MDL for D205-564/D430-688

We aren't changing the STC and invoking an MDL at this point. Don't bother with an MDL until we do an STC change.

David

From: Peter Hum [mailto:phum@dartaero.com]

Sent: Tuesday, July 18, 2006 1:49 PM

To: 'David Shepherd'

Cc: Kim Johnston (Kim Johnston) **Subject:** MDL for D205-564/D430-688

David,

We are closing out the ECN for the run-on wearplates;

Currently the D205-564 and D430-688 installations DO NOT have MDL's. Do you think its required that we make new MDL's? Or can we go without an MDL?

Thanks

Peter